

US EPA ARCHIVE DOCUMENT

# Situation Photo Log

Friday, November 9, 2012

Kalamazoo River / Enbridge Spill

## Water / Sediment Temperatures

Location	Water Temp. (°F)	Sediment Temp. (°F)
C0.4 Boat Launch Gauge	42.02	42.04
Ceresco Dam Control Point Boom	39.99	44.98
C3.2 Boat Launch Gauge	41.02	42.93
C5 Boat Launch Gauge	41.91	42.15
E4 Boat Launch Gauge	45.43	44.43

Prepared by:  
Matthew Haak  
START-USEPA  
Situation Unit



1. MP5.45 LDB tar glob and sheen observed.



2. Ceresco Dam sheen and debris observed collecting along the control point boom.





3. C0.4 observed the sheen sweep/boom maintenance boom departing the launch.




4. MP10.5 LDB RI crew observed.





5. MP10.5 LDB RI crew observed.



6. Observed core logging.





7. Morrow Lake south cove observed the sweep boat operating.



8. Morrow Lake Delta Gate C and curtain.